- 1980

Air Quality Control Region VII 5555 West Loop, Waite 300 Bellaire, Texas 77401

February 4, 1980

Gulfco Incorporated County Road 756 Drawer O Freeport, Texas 77541

Dear Mr. Randolph:

On January 16, 1980, I conducted a compliance investigation at Gulfco Incorporated. On that date, I detected no violations of the Trules and regulations of the Texas Air Control Board.

If we can be of any aid to you, please contact our office.

Sincerely,

Jacque Austin
Environmental Quality Specialist

:kj

bcc: Compliance, File, Board

ACCOUNT NUMBER TEL-0010-1	SOURCE INVESTIGATION SYSTEM			
Date of Investigation 01 /16/80	•		No. SIS-4	<del></del>
01 Action Code Code Drazoria Jurisdiction 070			EX 🗔	DA []
Company Name, Location, Mailing Address	Facility Type	Enter Y	or N in each bo	ox
02 Gulfco Incorporated	Portable Unit	54	Cinciffrant	
63 Co Road 756	Federal Facility	54	Significant <u>Pollutants</u>	
04 1 mi North of S H 332	NSPS		PA	
05 Drawer O	NESHAPS		SO <sub>2</sub>	
lHraanort letas //341	EPA Major Source		HC	
3	EPA Minor Source	<b>136</b> ]	CO	55.
53	ELW WILLIAM POUTCE	<u>~</u>		3
08 16 30 Business/ Shinyard Fabricat	Other	65 66	Other 67	70
09 Group 16 18 20 Business/ Shipyard Fabrication and Repair 83 66 67 70 80 80 80				
10 INVESTIGATIONS: Agency Comment Alternate Method	Burning Per	mit	20 (Permit No	
	Sample Pro			
i i	rveillance Oth			
1 272	7.1			60
Investigator 070  11 Codes 16 19 22 Yechnical Report 25 Source 26 26 Source 26 Shipyard  12 Management Tom Randolph Title 40 Title	Superintend	ent ,71	4 233 =	47 6371
12 Management Tom Randolph Title Shipyard Person Same	60	Phone (/_ 4	(3_)233	67
13 Contacted 18 Title 41	60	Phone (		
14 Complaint No. 16 22 Date Received 1 28 30 Odor 12	Smoke 33	Dust 🔲 0	ther	
	Smoke 33	<u></u>	ther	ı
Findings: Confirmed Unconfirmed Odor Smoke	· —	34	Cause	
REPRESENTATIVE SAMPLES	Sampling Resu			No
Турв Saurce Pollutant Time Acts	ual Aflo	wable %	of Max. % of	Norm.
16 16 25 25 32 37 41	49 51		61 64	
17 16 18 23 37 41 49 51 59 61 64				
18 16 18 23 37 37 41 49 31 59 61 64				
Emission Rate Code: lb/hr-01; lb/D-02; T/Y-03; SCFM-04; PPM-05; PPB-06; ug/M <sup>3</sup> -07; GR/SCF-08; lb/MBTU-09; %-10; None-11  19 Emissions Status: In Compliance Noncompliance Short-Term Noncompliance Undetermined				
19 Emissions Status: In Compliance Noncompliance 17 Short-Term Noncompliance 19 Undetermined 19 Undetermined 19 Undetermined, why? Plant Partial Needs Upset or Sample 22 Maintenance 23 Other 24 Other				
1 St. 1				- 1
20 Violations: Rule Rule Rule 36	Order 46		TCAA	
21 Source Source Source	Source	<u> </u>	Source 49	
22 Scheduled Date Action: 16 / 18 / 20 Comments 22				
23 Date / / Comments 22	.,			
24 PA SO HC 42 unc 49 cc	NO	con 66	69 unc	76 con
25 Compliance Action Recommended: Yes No 🗷	Abatement	Letter Sent:	Yes 🔲	No 🔲
Emissions Inventory Form Needed: Yes 20 No 11 El accurate: Yes 2	_		10	.,,
Permits: Approve Deny Exempt Hold D	2.5	44		
	Culturent.			
a grand water a fifty		17.		
nvestigator (s) Date		Approved		
		ъ.	1 of <sup>2</sup>	B '

TRE 000718

Investigator's Comments Bulfco Incorporated Freeport, Brazoria Co., Texas BL-0016-H 01-21-80 < 1/167 Page 2

On January 16, 1980, a biennial compliance investigation was conducted at Gulfco Incorporated in Freeport. This company was formerly named Chromallay. Mr. Tom Randolph, shipyard superintendent, represented the company.

Gulfco conducts a barge cleaning operation utilizing a dry sandblasting technique. The company also repairs barges and in the process, removes any liquid residue from them. Mr. Randolph estimated that the amount of time spent on barge cleaning and repair is, 10 and 90%, respectively. The cleaning and repair processes have not been changed since the previous investigation.

## Compliance Review

## Regulation I

131.03.01. In compliance. No outdoor burning on the property.

131.03.02. Go incinerator on the property.

131.03.03.03NA

131.03.04. NA

131.03.05.002. In compliance. No evidence of particulate emissions crossing the property line.

Regulations II, III, IV, V - NA

Regulation VI - This facility was built in 1969 prior to the permit system becoming effective.

Regulations VII, VIII, IX - NA

General Rule 131.01.00.005. The company spokesman is aware of the facility's potential for creating a nuisance. One complaint (regarding noxious fumes) was received during 1979, but not verified. No obnoxious odors apparent during my investigation.

A letter stating compliance c TACB rules and regulations on the date of this investigation has been forwarded to the company per Mr. Randolph's request.

On the day of this investigation this facility appeared to be in compliance with rules and regulations of TACB.

Jacque Austin

E.Q.S. Region VII